3. The work done by the machine is the difference between the heat supplied and the heat rejected.

$$W = Q_H - Q_L$$

$$W = 700\ J - 500\ J = 200\ J$$