

WELDING SYMBOLS 1

SUPPLEMENTARY SYMBOLS USED WITH WELDING SYMBOLS

LOCATION OF ELEMENTS OF A WELDING SYMBOL





SUPPLEMENTARY SYMBOLS

WELD-ALL-	FIELD WELD	MELT- THRU	BACKING, SPACER`	CONTOUR		
AROUND				FLUSH	CONVEX	CONCAVE
	1			_		

BASIC WELDING SYMBOLS AND THEIR LOCATION SIGNIFICANCE LOCATION SIGNIFICANCE NO ARROW SIDE OR OTHER SIDE SIGNIFICANCE ARROW SIDE OTHER SIDE BOTH SIDES NOT FILLET USED NOT USED NOT PLUG OR SLOT USED SPOT OR NOT PROJECTION USED 0 NOT SEAM USED GROOVE WELL BACK OR BACKING SYMBOL NOT NOT USED GROOVE WELD I USED NOT NOT NOT SURFACING USED USED USED SCARF FOR NOT BRAZED JOINT USED FLANGE NOT USED NOT EDGE USED FLANGE NOT NOT CORNER USED USED SQUARE NOT ٧ USED NOT BEVEL USED NOT USED U NOT J H USED NOT FLARE-V USED FLARE-BEVEL NOT USED

DESIGN OF STANDARD SYMBOLS

