ANSWER KEY TO CHALLENGE SHEET

LIGHTING SYSTEMS CHALLENGE 1

Customer's Concern: I put in new headlight bulbs just a few days ago, but the lights are still very dim.

Customer Vehicle: Dodge Grand Caravan.

Possible Causes of This Challenge:

- 1. Excessive resistance in headlight feed circuit.
- 2. Excessive resistance in headlight ground circuit.
- **3.** Excessive resistance in body ground circuit.

Safety First Practices to Follow:

- 1. Wear safety glasses at all times.
- 2. Use caution when handling halogen lamps; do not touch glass part.

Tools and Equipment Required:

1. Digital multimeter.