

## ANSWER KEY TO CHALLENGE SHEET

### CV JOINT CHALLENGE

**Customer's Concern:** My vehicle shudders when turning right. This noise is getting worse.

**Customer Vehicle:** Ford Ranger.

#### Possible Causes of This Challenge:

1. Worn right outer CV joint.
2. Torn right outer CV boot.

#### Safety First Practices to Follow:

1. Wear safety glasses at all times.
2. Follow all safety rules when using hand tools.
3. Always follow lift operating instructions.

#### Tools and Equipment Required:

1. Hand tools.
2. CV boot pliers.