

ANSWER KEY TO CHALLENGE SHEET

TRANSAXLE REMOVAL CHALLENGE

Customer's Concern: My vehicle will not move. The engine revs, but the transmission will not engage.

Customer Vehicle: Nissan Altima.

Possible Causes of This Challenge:

1. Worn clutch disc.
2. Defective pressure plate.
3. Internal transmission damage.

Safety First Practices to Follow:

1. Wear safety glasses at all times.
2. Follow all safety rules when using hand tools.
3. Do not breathe in clutch dust.
4. Always follow lift operating instructions.

Tools and Equipment Required:

1. Hand tools.
2. Transmission jack.
3. Clutch alignment tool.