

Example Ø 16N7/h6

Hole Size Ø 15.995
15.977

Shaft Size Ø 16.000
15.989

Max. Clearance 0.006

Max. Interference 0.023

Example Ø 45U7/h6

Hole Size Ø 44.939
44.914

Shaft Size Ø 45.000
44.984

Min. Interference 0.045

Max. Interference 0.086

PREFERRED SHAFT BASIS TRANSITION AND INTERFERENCE FITS																
UPTO AND INCLUDING		LOCATIONAL TRANSN.			LOCATIONAL TRANSN.			LOCATIONAL INTERF.			MEDIUM DRIVE			FORCE		
		Hole K7	Shaft h6	Fit	Hole N7	Shaft h6	Fit	Hole P7	Shaft h6	Fit	Hole S7	Shaft h6	Fit	Hole U7	Shaft h6	Fit
1	MAX	1.000	1.000	0.006	0.996	1.000	0.002	0.994	1.000	0.000	0.986	1.000	-0.008	0.982	1.000	-0.012
	MIN	0.990	0.994	-0.010	0.986	0.994	-0.014	0.984	0.994	-0.016	0.976	0.994	-0.024	0.972	0.994	-0.028
1.2	MAX	1.200	1.200	0.006	1.196	1.200	0.002	1.194	1.200	0.000	1.186	1.200	-0.008	1.182	1.200	-0.012
	MIN	1.190	1.194	-0.010	1.186	1.194	-0.014	1.184	1.194	-0.016	1.176	1.194	-0.024	1.172	1.194	-0.028
1.6	MAX	1.600	1.600	0.006	1.596	1.600	0.002	1.594	1.600	0.000	1.586	1.600	-0.008	1.582	1.600	-0.012
	MIN	1.590	1.594	-0.010	1.586	1.594	-0.014	1.584	1.594	-0.016	1.576	1.594	-0.024	1.572	1.594	-0.028
2	MAX	2.000	2.000	0.006	1.996	2.000	0.002	1.994	2.000	0.000	1.986	2.000	-0.008	1.982	2.000	-0.012
	MIN	1.990	1.994	-0.010	1.986	1.994	-0.014	1.984	1.994	-0.016	1.976	1.994	-0.024	1.972	1.994	-0.028
2.5	MAX	2.500	2.500	0.006	2.496	2.500	0.002	2.494	2.500	0.000	2.486	2.500	-0.008	2.482	2.500	-0.012
	MIN	2.490	2.494	-0.010	2.486	2.494	-0.014	2.484	2.494	-0.016	2.476	2.494	-0.024	2.472	2.494	-0.028
3	MAX	3.000	3.000	0.006	2.996	3.000	0.002	2.994	3.000	0.000	2.986	3.000	-0.008	2.982	3.000	-0.012
	MIN	2.990	2.994	-0.010	2.986	2.994	-0.014	2.984	2.994	-0.016	2.976	2.994	-0.024	2.972	2.994	-0.028
4	MAX	4.003	4.000	0.011	3.996	4.000	0.004	3.992	4.000	0.000	3.985	4.000	-0.007	3.981	4.000	-0.011
	MIN	3.991	3.992	-0.009	3.984	3.992	-0.016	3.980	3.992	-0.020	3.973	3.992	-0.027	3.969	3.992	-0.031
5	MAX	5.003	5.000	0.011	4.996	5.000	0.004	4.992	5.000	0.000	4.985	5.000	-0.007	4.981	5.000	-0.011
	MIN	4.991	4.992	-0.009	4.984	4.992	-0.016	4.980	4.992	-0.020	4.973	4.992	-0.027	4.969	4.992	-0.031
6	MAX	6.003	6.000	0.011	5.996	6.000	0.004	5.992	6.000	0.000	5.985	6.000	-0.007	5.981	6.000	-0.011
	MIN	5.991	5.992	-0.009	5.984	5.992	-0.016	5.980	5.992	-0.020	5.973	5.992	-0.027	5.969	5.992	-0.031
8	MAX	8.005	8.000	0.014	7.996	8.000	0.005	7.991	8.000	0.000	7.983	8.000	-0.008	7.978	8.000	-0.013
	MIN	7.990	7.991	-0.010	7.981	7.991	-0.019	7.976	7.991	-0.024	7.968	7.991	-0.032	7.963	7.991	-0.037
10	MAX	10.005	10.000	0.014	9.996	10.000	0.005	9.991	10.000	0.000	9.983	10.000	-0.008	9.978	10.000	-0.013
	MIN	9.990	9.991	-0.010	9.981	9.991	-0.019	9.976	9.991	-0.024	9.968	9.991	-0.032	9.963	9.991	-0.037
12	MAX	12.006	12.000	0.017	11.995	12.000	0.006	11.989	12.000	0.000	11.979	12.000	-0.010	11.974	12.000	-0.015
	MIN	11.988	11.989	-0.012	11.977	11.989	-0.023	11.971	11.989	-0.029	11.961	11.989	-0.039	11.950	11.989	-0.044
16	MAX	16.006	16.000	0.017	15.995	16.000	0.006	15.989	16.000	0.000	15.979	16.000	-0.010	15.974	16.000	-0.015
	MIN	15.988	15.989	-0.012	15.977	15.989	-0.023	15.971	15.989	-0.029	15.961	15.989	-0.039	15.956	15.989	-0.044
20	MAX	20.006	20.000	0.019	19.993	20.000	0.006	19.986	20.000	-0.001	19.973	20.000	-0.014	19.967	20.000	-0.020
	MIN	19.985	19.987	-0.015	19.972	19.987	-0.028	19.965	19.987	-0.035	19.952	19.987	-0.048	19.946	19.987	-0.054
25	MAX	25.006	25.000	0.019	24.993	25.000	0.006	24.986	25.000	-0.001	24.973	25.000	-0.014	24.966	25.000	-0.027
	MIN	24.985	24.987	-0.015	24.972	24.987	-0.028	24.965	24.987	-0.035	24.952	24.987	-0.048	24.939	24.987	-0.061
30	MAX	30.006	30.000	0.019	29.993	30.000	0.006	29.986	30.000	-0.001	29.973	30.000	-0.014	29.966	30.000	-0.027
	MIN	29.985	29.987	-0.015	29.972	29.987	-0.028	29.965	29.987	-0.035	29.952	29.987	-0.048	29.939	29.987	-0.061
40	MAX	40.007	40.000	0.023	39.992	40.000	0.008	39.983	40.000	-0.001	39.966	40.000	-0.018	39.949	40.000	-0.035
	MIN	39.982	39.984	-0.018	39.967	39.984	-0.033	39.958	39.984	-0.042	39.941	39.984	-0.059	39.924	39.984	-0.076
50	MAX	50.007	50.000	0.023	49.992	50.000	0.008	49.983	50.000	-0.001	49.966	50.000	-0.018	49.939	50.000	-0.045
	MIN	49.982	49.984	-0.018	49.967	49.984	-0.033	49.958	49.984	-0.042	49.941	49.984	-0.059	49.914	49.984	-0.086
60	MAX	60.009	60.000	0.028	59.991	60.000	0.010	59.979	60.000	-0.002	59.958	60.000	-0.023	59.924	60.000	-0.057
	MIN	59.979	59.981	-0.021	59.961	59.981	-0.039	59.949	59.981	-0.051	59.928	59.981	-0.072	59.894	59.981	-0.106
80	MAX	80.009	80.000	0.028	79.991	80.000	0.010	79.979	80.000	-0.002	79.952	80.000	-0.029	79.909	80.000	-0.072
	MIN	79.979	79.981	-0.021	79.961	79.981	-0.039	79.949	79.981	-0.051	79.922	79.981	-0.078	79.879	79.981	-0.121
100	MAX	100.010	100.000	0.032	99.990	100.000	0.012	99.976	100.000	-0.002	99.942	100.000	-0.036	99.889	100.000	-0.089
	MIN	99.975	99.978	-0.025	99.955	99.978	-0.045	99.941	99.978	-0.059	99.907	99.978	-0.093	99.854	99.978	-0.146
120	MAX	120.010	120.000	0.032	119.990	120.000	0.012	119.976	120.000	-0.002	119.934	120.000	-0.044	119.869	120.000	-0.109
	MIN	119.975	119.978	-0.025	119.955	119.978	-0.045	119.941	119.978	-0.059	119.899	119.978	-0.101	119.834	119.978	-0.166
160	MAX	160.012	160.000	0.037	159.988	160.000	0.013	159.972	160.000	-0.003	159.915	160.000	-0.060	159.825	160.000	-0.150
	MIN	159.972	159.975	-0.028	159.948	159.975	-0.052	159.932	159.975	-0.068	159.875	159.975	-0.125	159.785	159.975	-0.215

Table 49 Preferred shaft basis fits. (Dimensions in millimeters.) (continued)