

CONTENTS

Preface x

Chapter 1

Magnetic Circuits and Magnetic Materials 1

- 1.1 Introduction to Magnetic Circuits 2
- 1.2 Flux Linkage, Inductance, and Energy 11
- 1.3 Properties of Magnetic Materials 19
- 1.4 AC Excitation 23
- 1.5 Permanent Magnets 30
- 1.6 Application of Permanent Magnet Materials 35
- 1.7 Summary 42
- 1.8 Problems 43

Chapter 2

Transformers 57

- 2.1 Introduction to Transformers 57
- 2.2 No-Load Conditions 60
- 2.3 Effect of Secondary Current; Ideal Transformer 64
- 2.4 Transformer Reactances and Equivalent Circuits 68
- 2.5 Engineering Aspects of Transformer Analysis 73
- 2.6 Autotransformers; Multiwinding Transformers 81
- 2.7 Transformers in Three-Phase Circuits 85
- 2.8 Voltage and Current Transformers 90
- 2.9 The Per-Unit System 95
- 2.10 Summary 103
- 2.11 Problems 104

Chapter 3

Electromechanical-Energy-Conversion Principles 112

- 3.1 Forces and Torques in Magnetic Field Systems 113
- 3.2 Energy Balance 117
- 3.3 Energy in Singly-Excited Magnetic Field Systems 119
- 3.4 Determination of Magnetic Force and Torque from Energy 123
- 3.5 Determination of Magnetic Force and Torque from Coenergy 129
- 3.6 Multiply-Excited Magnetic Field Systems 136
- 3.7 Forces and Torques in Systems with Permanent Magnets 142
- 3.8 Dynamic Equations 151
- 3.9 Analytical Techniques 155
- 3.10 Summary 158
- 3.11 Problems 159

Chapter 4

Introduction to Rotating Machines 173

- 4.1 Elementary Concepts 173
- 4.2 Introduction to AC and DC Machines 176
- 4.3 MMF of Distributed Windings 187
- 4.4 Magnetic Fields in Rotating Machinery 197
- 4.5 Rotating MMF Waves in AC Machines 201
- 4.6 Generated Voltage 208
- 4.7 Torque in Nonsalient-Pole Machines 214
- 4.8 Linear Machines 227
- 4.9 Magnetic Saturation 230

- 4.10 Leakage Fluxes 233
- 4.11 Summary 235
- 4.12 Problems 237

Chapter 5

Synchronous Machines 245

- 5.1 Introduction to Polyphase Synchronous Machines 245
- 5.2 Synchronous-Machine Inductances; Equivalent Circuits 248
- 5.3 Open- and Short-Circuit Characteristics 256
- 5.4 Steady-State Power-Angle Characteristics 266
- 5.5 Steady-State Operating Characteristics 275
- 5.6 Effects of Salient Poles; Introduction to Direct- and Quadrature-Axis Theory 281
- 5.7 Power-Angle Characteristics of Salient-Pole Machines 289
- 5.8 Permanent-Magnet AC Motors 293
- 5.9 Summary 295
- 5.10 Problems 297

Chapter 6

Polyphase Induction Machines 306

- 6.1 Introduction to Polyphase Induction Machines 306
- 6.2 Currents and Fluxes in Polyphase Induction Machines 311
- 6.3 Induction-Motor Equivalent Circuit 313
- 6.4 Analysis of the Equivalent Circuit 317
- 6.5 Torque and Power by Use of Thevenin's Theorem 322
- 6.6 Parameter Determination from No-Load and Blocked-Rotor Tests 330
- 6.7 Effects of Rotor Resistance; Wound and Double-Squirrel-Cage Rotors 340
- 6.8 Summary 347
- 6.9 Problems 348

Chapter 7

DC Machines 357

- 7.1 Introduction 357
- 7.2 Commutator Action 364
- 7.3 Effect of Armature MMF 367
- 7.4 Analytical Fundamentals: Electric-Circuit Aspects 370
- 7.5 Analytical Fundamentals: Magnetic-Circuit Aspects 374
- 7.6 Analysis of Steady-State Performance 379
- 7.7 Permanent-Magnet DC Machines 384
- 7.8 Commutation and Interpoles 390
- 7.9 Compensating Windings 393
- 7.10 Series Universal Motors 395
- 7.11 Summary 396
- 7.12 Problems 397

Chapter 8

Variable-Reluctance Machines and Stepping Motors 407

- 8.1 Basics of VRM Analysis 408
- 8.2 Practical VRM Configurations 415
- 8.3 Current Waveforms for Torque Production 421
- 8.4 Nonlinear Analysis 430
- 8.5 Stepping Motors 437
- 8.6 Summary 446
- 8.7 Problems 448

Chapter 9

Single- and Two-Phase Motors 452

- 9.1 Single-Phase Induction Motors: Qualitative Examination 452
- 9.2 Starting and Running Performance of Single-Phase Induction and Synchronous Motors 455
- 9.3 Revolving-Field Theory of Single-Phase Induction Motors 463
- 9.4 Two-Phase Induction Motors 470

- 9.5 Summary 488
- 9.6 Problems 489

Chapter 10

Introduction to Power Electronics 493

- 10.1 Power Switches 494
- 10.2 Rectification: Conversion of AC to DC 507
- 10.3 Inversion: Conversion of DC to AC 538
- 10.4 Summary 550
- 10.5 Bibliography 552
- 10.6 Problems 552

Chapter 11

Speed and Torque Control 559

- 11.1 Control of DC Motors 559
- 11.2 Control of Synchronous Motors 578
- 11.3 Control of Induction Motors 595
- 11.4 Control of Variable-Reluctance Motors 613
- 11.5 Summary 616
- 11.6 Bibliography 618
- 11.7 Problems 618

Appendix A

Three-Phase Circuits 628

- A.1 Generation of Three-Phase Voltages 628
- A.2 Three-Phase Voltages, Currents, and Power 631
- A.3 Y- and Δ -Connected Circuits 635
- A.4 Analysis of Balanced Three-Phase Circuits; Single-Line Diagrams 641
- A.5 Other Polyphase Systems 643

Appendix B

Voltages, Magnetic Fields, and Inductances of Distributed AC Windings 644

- B.1 Generated Voltages 644
- B.2 Armature MMF Waves 650
- B.3 Air-Gap Inductances of Distributed Windings 653

Appendix C

The dq0 Transformation 657

- C.1 Transformation to Direct- and Quadrature-Axis Variables 657
- C.2 Basic Synchronous-Machine Relations in dq0 Variables 660
- C.3 Basic Induction-Machine Relations in dq0 Variables 664

Appendix D

Engineering Aspects of Practical Electric Machine Performance and Operation 668

- D.1 Losses 668
- D.2 Rating and Heating 670
- D.3 Cooling Means for Electric Machines 674
- D.4 Excitation 676
- D.5 Energy Efficiency of Electric Machinery 678

Appendix E

Table of Constants and Conversion Factors for SI Units 680

Index 681